

4.2 NOISE LEVELS

WARNING

Constant high noise levels – ear protection must be worn. **HEARING HAZARD EXCEEDS 90 dB (A)**

May cause loss or degradation of hearing over a period.

Always ensure that operators are provided with ear defenders of approved pattern and that these are always worn when the machine is operating.

